


AUDI A4: 1HEJ578

Vinnumber:	WAUZZZ8K6FN003193	Versionname:	A4 BER Ultra 136PK
First Registrationdate:	1/07/2014	Fiscalpower:	
Expertise Mileage:	160912	Power Kw:	100
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	KT
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	DVD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		0,00
Seat cover R R, Deformed / Strained, Acceptable		0,00



Tailgate, Dent(s) and scratch(es), Acceptable

0,00



Door R L, Scratch(es), Acceptable

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Wing R L, Dent(s) and scratch(es), Acceptable

0,00



Windscreen, Repaired, P - Check

0,00



Roof, Stone chip(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Backrest cover F R, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), LI - Repair and paint (complete)

0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Backrest cover F L, Worn, Acceptable

0,00



Seat cover F R, Worn, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Headlight L, Scratch(es), E - Replace

0,00



Bumper R, Dent(s) and scratch(es), Acceptable

0,00



Outer door handle F R, Scratch(es), Acceptable

0,00



Wing F L, Stone chip(s), Acceptable

0,00



Rearview mirror housing R, Stone chip(s), Acceptable

0,00



Seat cover F L, Worn, Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

