


**AUDI Q5: 1LLY101**

Vinnumber:	<b>WAUZZZ8R3GA066726</b>	Versionname:	<b>2.0 TDI 110KW</b>
First Registrationdate:	<b>23/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>181160</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>EX POOL</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/17/108 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>432,24</b>
-------------------	---------------

Rear spoiler, Chemical polution, Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>350,16</b>
---	---------------




Bumper grille, Broken, E - Replace 34,08



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door moulding Lower R R, Deformed / Strained, E - Replace 0,00



Door moulding Lower F R, Scratch(es), E - Replace 0,00



Gear shift lever knob, Worn, Acceptable 0,00

*No pictures to display*

Roof, Chemical pollution, Acceptable 0,00

*No pictures to display*

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper spoiler F, Dent(s) and scratch(es), E - Replace 48,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*