



**AUDI A5 SPORTBACK: 1VKG550**

Vinnumber:	<b>WAUZZZF51KA019140</b>	Versionname:	<b>2.0 TDI 110kW S tronic Business Edition</b>
First Registrationdate:	<b>4/12/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>29709</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>PARKING KT</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-Alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>245/40/18/97 W LightMetal</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Vredestein: 7 mm</b>	Re.R.	<b>Vredestein: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1907,20</b>
-------------------	----------------

Door R L, Scratch(es), 67 - Polish	<b>0,00</b>
------------------------------------	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

No pictures to display

Wing F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

