



BMW 5 BERLINE: 1LPP266

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA5E31020G040785 | Versionname: | 2.0 518D (100KW) |
| First Registrationdate: | 6/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 105622 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2408 |
| Maintenance: | 18000KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|----------------------------------|-----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | | Seats electric F R |
| GPS storage | HD | Central consol F |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|---------------------|-------|---------------------|
| 225/55/17/101 V LightMetal | | | | |
| Winter tyres: | Fr.L. | Kleber: 5 mm | Fr.R. | Kleber: 5 mm |
| | Re.L. | Kleber: 5 mm | Re.R. | Kleber: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | | |
|----------------------------------|--|------|
| Total cost ex VAT | | 0,00 |
| Bonnet, Scratch(es), 67 - Polish | | 0,00 |



Alloy rim F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Seat F L compl, Worn, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

