



BMW 3 BERLINE: 1KKA509

Vinnumber:	WBA3W31030K315775	Versionname:	2.0 316D (85KW) BERLINE
First Registrationdate:	18/05/2015	Fiscalpower:	
Expertise Mileage:	139986	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2123
Maintenance:	1300 KM OF 5-2020		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/16/95 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1638,42

Tailgate, Scratch(es), 67 - Polish 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F L, Worn, Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Dent(s), Acceptable

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Door frame R R, Dent(s), It - Spot repair

115,56



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Bumper R, Deformed / Strained, Le - Replace and paint

651,00



Alloy rim F R, Scratch(es), Acceptable

0,00

