



BMW 3 GRAN TURISMO: 1LGL171

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | WBA3Y11050D902045 | Versionname: | 2.0 318D (105KW) GRAN TURISMO |
| First Registrationdate: | 22/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 145000 | Power Kw: | 105 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | LKW3 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|---------------------|-------|---------------------|
| 225/55/17/92 MS LightMetal | | | | |
| Winter tyres: | Fr.L. | Dunlop: 5 mm | Fr.R. | Dunlop: 5 mm |
| | Re.L. | Dunlop: 6 mm | Re.R. | Dunlop: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|---------------------------------------|---------------|
| Total cost ex VAT | 294,60 |
| Rear window, Scratch(es), E - Replace | 0,00 |



Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Seat cover F L, Damaged, Acceptable 0,00



Bumper R, Dent(s), LI - Repair and paint (complete) 235,80

