


MERCEDES GLE: 1NTL467

Vinnumber:	WDC1660041A736124	Versionname:	2.1 GLE 250 D 4MATIC
First Registrationdate:	22/04/2016	Fiscalpower:	
Expertise Mileage:	186112	Power Kw:	150
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	GEBOUW BUUR
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	Tow bar fixed
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Total cost ex VAT	759,80
Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Rearview mirror basis R, Scratch(es), Smart repair	110,64



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Door F R, Repaired, Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper moulding F, Scratch(es), E - Replace 0,00

