



SKODA Octavia: 1FOW237

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | TMBJG7NE7E0043836 | Versionname: | OCTAVIA COMBI Ambition 105PK |
| First Registrationdate: | 10/09/2013 | Fiscalpower: | |
| Expertise Mileage: | 48812 | Power Kw: | 77 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4211 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Windows electric F | Central consol F | |
| Windows electric R | Luggage cover | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar removable |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|---------------------|-------|---------------------|
| 205/55/16/91 V Steel | | | | |
| Summer tyres: | Fr.L. | Dunlop: 4 mm | Fr.R. | Dunlop: 4 mm |
| | Re.L. | Dunlop: 4 mm | Re.R. | Dunlop: 4 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---------------------------------------|---------------|
| Total cost ex VAT | 853,78 |
| Wheel cover R L, Missing, E - Replace | 30,00 |



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Not original part, Acceptable 0,00

No pictures to display