



| | | | |
|------------------------------------|--------------------------|--------------|-----------------------|
| VOLVO V60: 1LAH423 | | | |
| Vinnumber: | VV1FW31A1F1269869 | Versionname: | 2.0 D3 KINETIC |
| First Registrationdate: | 31/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 170436 | Power Kw: | 100 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1304 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Options | | | |
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar fixed |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|---------------------|-------|---------------------|
| Degree of wear | | | | |
| | 215/55/16/97 H LightMetal | | | |
| Winter tyres: | Fr.L. | Kleber: 5 mm | Fr.R. | Kleber: 5 mm |
| | Re.L. | Kleber: 5 mm | Re.R. | Kleber: 5 mm |

| | | | |
|---|------------|------------|--------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 95,00 |
| Bonnet, Dent(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door R R, Dent(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim R L, Scratch(es), H. Dent(s) and paint (complete) | | | 05,00 |

Alloy rim K L, Scratch(es), LI - repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Bad repair, E - Replace

0,00

