



BMW 3 TOURING: 1LLN063

Vinnumber:	WBA8H71090K682297	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	21/10/2015	Fiscalpower:	
Expertise Mileage:	139469	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	PLUS 12000 KM	Parking lot:	4413
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment


Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	1748,29
Door R R, Scratch(es), 67 - Polish	0,00



Roof, Dent(s), PDR - Paintless dent repair

142,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80




Ceiling, Stain, Cleaning

25,00



Spoiler R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door panel R L, Scratch(es), Acceptable

0,00



Tyre repair kit, Missing, E - Replace

210,53



Door F L, Scratch(es), 67 - Polish

0,00

Door F L, Scratch(es), or - Polish

0,00



Windscreen, Scratch(es), Acceptable

0,00



Wing F L, Dent(s) and scratch(es), Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Bumper F, Hole, Le - Replace and paint

735,00



Wing F R, Scratch(es), Acceptable

0,00

