



BMW 3 TOURING: 1LSU232

Vinnumber:	WBA8H71010K682276	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	25/11/2015	Fiscalpower:	
Expertise Mileage:	31004	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	1/09/2018	Parking lot:	PARKING KT
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1958,18

Alloy rim F L, Scratch(es), Acceptable 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00




Door F R, Scratch(es), 67 - Polish

50,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Maintenance, Maintenance, Execute

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20





Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68

