



<b>BMW X3: 1LES876</b>			
Vinnumber:	<b>WBAWZ310600F65479</b>	Versionname:	<b>2.0 SDRIVE18D (100KW)</b>
First Registrationdate:	<b>8/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>143110</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3828</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		


<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
Winter tyres:	<b>245/50/18/100 H LightMetal</b>			
	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

<b>Assistance equipment</b>			
Number of charging cables (normal)	<b>0</b>	Runflat	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>0,00</b>
Roof, Chemical polution, 67 - Polish	<b>0,00</b>





Door R L, Dent(s) and scratch(es), Acceptable

0,00



Internal Boot Lining L, Broken, Acceptable

0,00



Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Backrest cover F L, Worn, Acceptable

0,00




Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable

0,00



Door R R, Dent(s) and scratch(es), Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00

