


**BMW 3: 1HSN481**

Vinnnumber:	<b>WBA3E11000P657906</b>	Versionname:	<b>3 BER 320dA Eff.Dynamics Ed.163PK Aut.</b>
First Registrationdate:	<b>23/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>145132</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3523</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>138,00</b>
Protection plate M, Tear, E - Replace			<b>0,00</b>



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Foglight R, Broken, E - Replace 138,00



Windscreen, Repaired, Acceptable 0,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Bumper R, Dent(s), Acceptable 0,00

