


BMW 5 BERLINE: 1LRV058

Vinnumber:	WBA5E31010G040812	Versionname:	2.0 518D (100KW)
First Registrationdate:	20/11/2015	Fiscalpower:	
Expertise Mileage:	89025	Power Kw:	100
Bodytype:	Berline	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 9000 KM	Parking lot:	4509
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			759,72
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Ignition key, Missing, E - Replace

150,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Tailgate ram L, Not functioning (well), P - Check

0,00



Bodywork, Dirty, P - Check

0,00



Seat cover R, Dirty, Cleaning

50,00



Rearview mirror basis L, Scratch(es), Acceptable

0,00

