



BMW 5 TOURING: 1KXT855

Vinnumber:	WBA5L11050D786188	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	28/07/2015	Fiscalpower:	
Expertise Mileage:	160096	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4523
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/18/96 Y LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1821,82

Rear window, Not original part, Remove lettering 25,00



Seat cover F L, Worn, Acceptable

0,00



Alloy rim R R polished, Scratch(es), I - Repair

155,00




Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L polished, Scratch(es), I - Repair

155,00



Alloy rim R L polished, Scratch(es), I - Repair

155,00



Bumper R, Scratch(es), Acceptable

0,00



Door panel F L, Worn, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Door F L, Dent(s), Acceptable

0,00



Windscreen, Scratch(es), E - Replace

560,64



Alloy rim F R polished, Scratch(es), I - Repair

155,00

