



**BMW 4 GRAN COUPE: YX7281**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>WBA4E71010G747024</b> | Versionname: | <b>2.0 418D (110KW) GRAN COUPE</b> |
| First Registrationdate:            | <b>14/12/2016</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>97921</b>             | Power Kw:    | <b>110</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                       |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>KT</b>                          |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>No</b>                |              |                                    |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>No GPS</b>                    |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>NOT OK</b> |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>     |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                     |           | Lighting            | <b>OK</b>     |
|                     |           | Wiperblades         | <b>OK</b>     |

**Degree of wear**

|                                  |       |       |                |
|----------------------------------|-------|-------|----------------|
| <b>225/50/17/94 H LightMetal</b> |       |       |                |
| Winter tyres:                    | Fr.L. | Fr.R. | Michelin: 4 mm |
|                                  | Re.L. | Re.R. | Michelin: 4 mm |

**Assistance equipment**

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                           |         |
|-------------------------------------------|---------|
| Total cost ex VAT                         | 1866,24 |
| Bumper F L, Scratch(es), It - Spot repair | 115,56  |



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Foglight L, Broken, E - Replace 156,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Door F R, Scratch(es), Acceptable 0,00

No pictures to display