



**BMW 5: 1HTC458**

|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:                         | <b>WBA5L310X0D677866</b> | Versionname: | <b>5 TOURING 520d 163PK</b> |
| First Registrationdate:            | <b>25/09/2014</b>        | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>203030</b>            | Power Kw:    | <b>120</b>                  |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>GEBOUW GEBUUR</b>        |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                       |                              | Central consol F      |                      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                      |
| GPS storage                    |                              | Front parking sensors |                      |
| Windows electric F             |                              | Rear parking sensors  |                      |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Cruise Control                 |                              |                       |                      |
| Steering wheel multifunctional |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/55/17/97 H LightMetal</b> |       |                          |       |                          |
| Winter tyres:                    | Fr.L. | <b>Michelin: 5 mm</b>    | Fr.R. | <b>Michelin: 5 mm</b>    |
|                                  | Re.L. | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|   |            |            |               |
|---|------------|------------|---------------|
| Repair kit  | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT   |            |            | <b>512,72</b> |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) |            |            | <b>302,16</b> |



Bumper F R, Scratch(es), It - Spot repair

115,56



Rear window, Scratch(es), E - Replace

0,00



Roof, Chemical polution, 67 - Polish

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

