



BMW 3 TOURING: 1LPA190

Vinnumber:	WBA8L71070K553103	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	3/11/2015	Fiscalpower:	
Expertise Mileage:	48535	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2531
Maintenance:	OVER 29000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 423,60

Wing F L, Scratch(es), 67 - Polish 0,00



Door F L, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Wing F R, Scratch(es), Acceptable

0,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00



Door R L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), Acceptable 0,00



Bonnet, Chemical polution, 67 - Polish 0,00



Door F R, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

