


BMW 5 BERLINE: 1LUH520

Vinnumber:	WBA5E31010G040891	Versionname:	2.0 518D (110KW)
First Registrationdate:	8/12/2015	Fiscalpower:	
Expertise Mileage:	98841	Power Kw:	110
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4533
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1782,38

Roof, Scratch(es), 67 - Polish 0,00

No pictures to display

Window F L door, Scratch(es), E - Replace 239,14



Windscreen, Scratch(es), E - Replace

560,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

420,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Scratch(es), LI - Repair and paint (complete)

372,60



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing F L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish

0,00

No pictures to display