



**CITROEN GRAND C4 PICASSO: 1LNY608**

Vinnumber:	<b>VF73ABHXMJ814980</b>	Versionname:	<b>1.6 BLUEHDI 115 S/S MAN6 BUSINESS</b>
First Registrationdate:	<b>2/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>150813</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3402</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	1377,06
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Wheel hub cap R L, Missing, E - Replace

15,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (complete)

310,50



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Tailgate, Scratch(es), It - Spot repair

115,56



Door trim R L, Crack, E - Replace

37,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20





Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

