


FORD KUGA: 1KUY571

Vinnnumber:	WF0AXXWPMAFE86728	Versionname:	2.0 TDCI 2WD 88KW TITANIUM
First Registrationdate:	9/07/2015	Fiscalpower:	
Expertise Mileage:	85107	Power Kw:	88
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2113
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/103 V LightMetal			
Winter tyres:	Fr.L.	Toyo: 6 mm	Fr.R.	Toyo: 6 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			848,05
Engine protective plate, Hole, E - Replace			80,80



Bumper trim R, Scratch(es), E - Replace

195,23



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display