



CITROEN Berlingo: 1JFY653

Vinnumber:	VF77B9HN0EJ832227	Versionname:	BERLINGO B/F Kort Fresh GPS 75PK
First Registrationdate:	8/12/2014	Fiscalpower:	
Expertise Mileage:	10624	Power Kw:	55
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4230
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	415,79
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Bad repair, Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Deformed / Strained, E - Replace	74,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bumper R, Dent(s), Smart repair

110,64



Trunk door R L, Dent(s), Acceptable

0,00

No pictures to display

Sliding door R, Scratch(es), Acceptable

0,00

No pictures to display