



MERCEDES A180: 1PUS474

Vinnumber:	WDD1760121J497336	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	23/09/2016	Fiscalpower:	
Expertise Mileage:	49266	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	EX POOL
Maintenance:	ASS B3 PLUS 298 D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1780,91
-------------------	----------------

Tailgate, Not original part, Sticker removal	25,00
--	--------------



Bumper R, Dent(s), LI - Repair and paint (complete)

259,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Wheel cover F R, Scratch(es), E - Replace

30,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), It - Spot repair

115,56



Wheel cover F L, Scratch(es), E - Replace

30,00



Door panel R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00

