


FORD TRANSIT CONNECT: 1KBR368

Vinnumber:	WF0RXXWPGRFK83749	Versionname:	1.6 TDCI 71KW (T200) TREND
First Registrationdate:	26/03/2015	Fiscalpower:	
Expertise Mileage:	162008	Power Kw:	70
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4117
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/55/16/97 V Steel			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1314,01
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Hole, Smart repair	110,64



Door F L, Scratch(es), LI - Repair and paint (complete)

238,76



Wheel cover F R, Scratch(es), E - Replace

22,50



Windscreen, Repaired, Acceptable

0,00



Trunk door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

158,85



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13






Roof, Scratch(es), LI - Repair and paint (complete) 361,13



Floor covering F L, Hole, E - Replace 237,00



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R R, Missing, E - Replace 20,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical pollution, 67 - Polish 0,00

No pictures to display