



MERCEDES CLA: 1PNU525

Vinnumber:	WDD1179081N412746	Versionname:	2.1 CLA 200 D URBAN
First Registrationdate:	17/08/2016	Fiscalpower:	
Expertise Mileage:	166241	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	EX POOL
Maintenance:	A3 IN 300 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	922,44
--------------------------	---------------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 25,00



Door F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Tyre repair kit, Missing, E - Replace 210,53



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Door R R, Dent(s), LI - Repair and paint (complete) 318,35



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), 67 - Polish 0,00

No pictures to display

No pictures to display

Door F R, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
--	-------------

No pictures to display

Bumper corner R R, Scratch(es), 67 - Polish	0,00
--	-------------

No pictures to display