



CITROEN C4 Picasso: 1HSR502

Vinnumber:	VF73A9HC8EJ769464	Versionname:	GR.C4 PICASSO Business GPS 115PK
First Registrationdate:	23/09/2014	Fiscalpower:	
Expertise Mileage:	117401	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1222
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	928,05
--------------------------	---------------

Bonnet, Repaired, Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Hole, E - Replace 264,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Smart repair 110,64



Door panel R R, Scratch(es), Smart repair 110,64



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Repaired, Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display