



**FORD Transit 350L: 1FXK504**

Vinnumber:	<b>WF0XXXTFXDU86702</b>	Versionname:	<b>TRANSIT B/F 350L LWB RWD Ambiente 125PK</b>
First Registrationdate:	<b>27/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>278086</b>	Power Kw:	<b>92</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV15</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>No climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/75/16/114 R Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	570,96
Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15



Ignition key, Missing, E - Replace

150,00

No pictures to display

Bumper F, Bad repair, Acceptable

0,00



Trunk door R R, Dent(s), It - Spot repair

115,56



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Aerial, Damaged, E - Replace

11,25



Bumper R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Roof, Rust, Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Scratch(es), Acceptable

0,00

No pictures to display

Trunk door R L, Dent(s), PDR - Paintless dent repair

63,00

