


**JAGUAR XF: 1LUU053**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>SAJBB4DN8GCV08588</b> | Versionname: | <b>2.0D 120KW PRESTIGE</b> |
| First Registrationdate:            | <b>10/12/2015</b>        | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>104303</b>            | Power Kw:    | <b>120</b>                 |
| Bodytype:                          |                          | Body color:  | <b>Black</b>               |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3324</b>                |
| Battery functioning:               | <b>Yes</b>               |              |                            |
| Number of doors:                   | <b>4</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Windows electric F             | Central consol F                 |
| Windows electric R             |                                  |
| Cruise Control                 |                                  |
| Steering wheel multifunctional |                                  |
| Seats F heated                 |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting LED</b>          |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                         |       |                         |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| <b>225/55/17/92 H LightMetal</b> |       |                         |       |                         |
| Summer tyres:                    | Fr.L. | <b>Vredestein: 4 mm</b> | Fr.R. | <b>Vredestein: 4 mm</b> |
|                                  | Re.L. | <b>Vredestein: 5 mm</b> | Re.R. | <b>Vredestein: 5 mm</b> |

**Assistance equipment**

|   |            |      |               |
|---|------------|------|---------------|
| Emergency spare wheel   | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT   |            |      | <b>369,84</b> |
| Wing R L, Chemical polution, LI - Repair and paint (complete) |            |      | <b>369,84</b> |



Tailgate, Scratch(es), Acceptable

0,00

*No pictures to display*