



MINI 5D: 1XGG711

Vinnumber:	WMWXS510302E58804	Versionname:	1.5 COOPER
First Registrationdate:	21/10/2016	Fiscalpower:	
Expertise Mileage:	41628	Power Kw:	100
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3621
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F	Sun Roof electric	
Windows electric R	Panoramic roof	
Cruise Control	Central consol F	
Steering wheel multifunctional	Luggage cover	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/87 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
Registration Document, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical polution, LI - Repair and paint (complete)	0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

0,00



Roof pillar L, Chemical polution, LI - Repair and paint (complete)

0,00



Certificate Of Conformity, Missing, E - Replace

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

0,00



Bumper grille, Broken, E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Tailgate, Chemical polution, Acceptable

0,00

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

0,00



Door R L, Dent(s), PDR - Paintless dent repair

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

0,00

