



**JEEP GRAND CHEROKEE: NJ2507**

Vinnumber:	<b>1C4RJFCM7FC140270</b>	Versionname:	<b>3.0 V6 TD OVERLAND 4WD AUTO (184 KW)</b>
First Registrationdate:	<b>11/05/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>88239</b>	Power Kw:	<b>184</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>A12</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

TV/DVD screen R	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	<b>Tow bar removable</b>
Type of GPS	<b>Headlighting LED</b>
Type of Lining	<b>GPS big screen color</b>
Type of climate control	<b>Lining artificial leather</b>
Level control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>265/50/20/111 MS LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>938,40</b>
Door R R, Scratch(es), LI - Repair and paint (complete)	<b>382,02</b>



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Windscreen, Stone chip(s), Windscreen repair 58,80



Wing moulding F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F L, Scratch(es), It - Spot repair 115,56



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim R R polished, Rust, Acceptable 0,00

