



OPEL Astra: 1GVQ887

Vinnumber:	W0LPD5EA9EG063208	Versionname:	ASTRA SED ecoFLEX Enjoy St&St 95PK
First Registrationdate:	13/05/2014	Fiscalpower:	
Expertise Mileage:	105807	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1306
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/60/16/92 MS Steel			
	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1101,53

Bumper F, Bad repair, LI - Repair and paint (complete) 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Tailgate, Chemical pollution, LI - Repair and paint (complete)

301,68



Window F L door, Scratch(es), E - Replace

0,00



Door R L, Chemical pollution, LI - Repair and paint (complete)

318,35



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Window F R door, Scratch(es), E - Replace

0,00



Window R L door, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Window R R door, Scratch(es), E - Replace

0,00

