



MINI : 1PEN901

Vinnumber:	WMWXN110903851812	Versionname:	1.5 ONE D
First Registrationdate:	17/06/2016	Fiscalpower:	
Expertise Mileage:	98166	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	EX POOL
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

175/65/15/84 H LightMetal				
Summer tyres:	Fr.L.	Hankook: 7 mm	Fr.R.	Hankook: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4779,90
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Bumper R, Broken, Le - Replace and paint

651,00



Wing trim R R, Scratch(es), E - Replace

84,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing trim R L, Scratch(es), E - Replace

84,00



Bumper trim R, Dent(s) and scratch(es), Smart repair

110,64



Sill trim L, Broken, E - Replace

126,45



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Foglight L, Broken, E - Replace 138,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Bumper spoiler F, Scratch(es), It - Spot repair 115,56



Tyre F R, Deformed / Strained, E - Replace 132,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Sill trim R, Broken, E - Replace 126,45



Wing moulding F L, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,50

No pictures to display