



MERCEDES GLA: 1LFN888

Vinnumber:	WDC1569121J171362	Versionname:	1.5 GLA 180 CDI STYLE
First Registrationdate:	15/09/2015	Fiscalpower:	
Expertise Mileage:	32828	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1733
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1033,32
Wing trim R R, Scratch(es), E - Replace			72,00



Roof, Dent(s), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Door F R, Bad repair, LI - Repair and paint (complete)

254,68



Bumper F, Scratch(es), Acceptable

0,00



Tyre F R, Tear, E - Replace

110,40



GPS, Not functioning (well), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Alloy rim R R, Scratch(es), Acceptable

0,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

246,56

