


**RENAULT Trafic: 1HVN715**

|                                    |                                 |              |                                                 |
|------------------------------------|---------------------------------|--------------|-------------------------------------------------|
| Vinnumber:                         | <b>VF1FLF1A2EY786289</b>        | Versionname: | <b>TRAF.27 B/F2C L1H1 Gr.Conf.FAP(EU5)115PK</b> |
| First Registrationdate:            | <b>14/10/2014</b>               | Fiscalpower: |                                                 |
| Expertise Mileage:                 | <b>199646</b>                   | Power Kw:    | <b>84</b>                                       |
| Bodytype:                          | <b>Transporter</b>              | Body color:  | <b>White</b>                                    |
| Gearbox:                           | <b>MAN 6 VIT</b>                | Paint type:  | <b>Opaque</b>                                   |
| Transmission:                      | <b>Front</b>                    | Rims summer: | <b>Steel</b>                                    |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                       |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>LCV05</b>                                    |
| Number of doors:                   | <b>5</b>                        |              |                                                 |
| Number of seats:                   | <b>6</b>                        |              |                                                 |
| Number head rests:                 | <b>6</b>                        |              |                                                 |
| Rims summer:                       | <b>Steel</b>                    |              |                                                 |
| Category:                          | <b>Light Commercial Vehicle</b> |              |                                                 |
| Oil level:                         | <b>OK</b>                       |              |                                                 |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |                                                 |

**Options**

|                         |                               |                      |                      |
|-------------------------|-------------------------------|----------------------|----------------------|
| Radio CD                |                               | Central consol F     |                      |
| GPS storage             | <b>SD</b>                     | Rear parking sensors |                      |
| GPS storage             |                               | Type of Tow bar      | <b>Tow bar fixed</b> |
| Windows electric F      |                               |                      |                      |
| Radio multimedia        |                               |                      |                      |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                      |                      |
| Type of GPS             | <b>GPS big screen color</b>   |                      |                      |
| Type of Lining          | <b>Lining fabrics</b>         |                      |                      |
| Type of climate control | <b>Manual climate control</b> |                      |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                       |                   |       |                   |
|---------------|-----------------------|-------------------|-------|-------------------|
| Summer tyres: | 205/65/16/105 T Steel |                   |       |                   |
|               | Fr.L.                 | Continental: 5 mm | Fr.R. | Continental: 3 mm |
|               | Re.L.                 | Continental: 7 mm | Re.R. | Continental: 4 mm |

**Assistance equipment**

|                                          |            |
|------------------------------------------|------------|
| Spare wheel                              | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |
| Number of charging cables (rapid charge) | <b>0</b>   |

|                                                         |                |
|---------------------------------------------------------|----------------|
| Total cost ex VAT                                       | <b>3039,09</b> |
| Door F R, Scratch(es), LI - Repair and paint (complete) | <b>238,76</b>  |



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Trunk door panel R, Scratch(es), Acceptable

0,00



Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Ignition key, Missing, E - Replace

150,00

No pictures to display

Steering wheel, Worn, Acceptable

0,00





Trunk door R R, Scratch(es), It - Spot repair

115,56



Central pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,49



Roof, Deformed / Strained, LI - Repair and paint (complete)

649,13



Armrest F Mid, Worn, Acceptable

0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76







Door R R, Scratch(es), LI - Repair and paint (complete)

238,76



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Tear, E - Replace

300,00



Trunk door panel L, Scratch(es), Acceptable

0,00



Rocker panel inner F L, Scratch(es), Acceptable

0,00



Ceiling, Hole, Smart repair


64,32



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56





|                                          |      |
|------------------------------------------|------|
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
|------------------------------------------|------|

No pictures to display

|                                        |       |
|----------------------------------------|-------|
| Backrest cover F L, Hole, Smart repair | 64,32 |
|----------------------------------------|-------|



|                                               |      |
|-----------------------------------------------|------|
| Wing R L, Dent(s) and scratch(es), Acceptable | 0,00 |
|-----------------------------------------------|------|

No pictures to display

|                                      |       |
|--------------------------------------|-------|
| Wheel cover R R, Broken, E - Replace | 22,50 |
|--------------------------------------|-------|



|                                       |       |
|---------------------------------------|-------|
| Wheel cover F R, Missing, E - Replace | 22,50 |
|---------------------------------------|-------|



|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 231,15 |
|---------------------------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display