


RENAULT Kangoo Express: 1HNU871

Vinnumber:	VF1FW17BD51117875	Versionname:	KANGOO EXPR.B/F Confort 75PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	21184	Power Kw:	55
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3201
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1017,96
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15






Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Scratch(es), LI - Repair and paint (complete) 382,02



Trunk door R L, Dent(s), PDR - Paintless dent repair 63,00



Trunk door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Rearview mirror housing L, Crack, E - Replace 0,00

