


**SKODA SUPERB: LV5494**

|                         |                          |              |                                   |
|-------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber:              | <b>TMBAJ9NP1H7512865</b> | Versionname: | <b>2.0 CRTDI 140KW DSG6 STYLE</b> |
| First Registrationdate: | <b>5/12/2016</b>         | Fiscalpower: |                                   |
| Expertise Mileage:      | <b>142366</b>            | Power Kw:    | <b>140</b>                        |
| Bodytype:               |                          | Body color   | <b>Black</b>                      |
| Gearbox:                | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                    |
| Transmission:           | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                  |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                         |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>2732</b>                       |
| Number of doors         | <b>5</b>                 |              |                                   |
| Number of seats         | <b>5</b>                 |              |                                   |
| Number head rests       | <b>5</b>                 |              |                                   |
| Rims summer             | <b>Aluminium</b>         |              |                                   |
| Category                | <b>Passenger Car</b>     |              |                                   |
| Oil level               | <b>OK</b>                |              |                                   |

**Options**

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                       |                              | Seats electric F L    |                      |
| GPS storage                    | <b>HD</b>                    | Seats electric F R    |                      |
| GPS storage                    |                              | Central consol F      |                      |
| Windows electric F             |                              | Luggage cover         |                      |
| Windows electric R             |                              | Front parking sensors |                      |
| Cruise Control                 |                              | Rear parking sensors  |                      |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Seats F heated                 |                              |                       |                      |
| Radio multimedia               |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                      |       |                      |
|---------------|----------------------------------|----------------------|-------|----------------------|
|               | <b>215/55/17/94 W LightMetal</b> |                      |       |                      |
| Summer tyres: | Fr.L.                            | <b>Pirelli: 4 mm</b> | Fr.R. | <b>Pirelli: 4 mm</b> |
|               | Re.L.                            | <b>Pirelli: 6 mm</b> | Re.R. | <b>Pirelli: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                                                     |                |
|---------------------------------------------------------------------|----------------|
| Total cost ex VAT                                                   | <b>3693,66</b> |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | <b>308,20</b>  |



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35




Outer door handle F L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,50





|                                                           |         |
|-----------------------------------------------------------|---------|
| Door F R, Dent(s) and scratch(es), Le - Replace and paint | 1082,52 |
|-----------------------------------------------------------|---------|



|                              |       |
|------------------------------|-------|
| Boot carpet, Stain, Cleaning | 15,00 |
|------------------------------|-------|



|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|



|                                                    |      |
|----------------------------------------------------|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------------|------|

No pictures to display

|                                                         |        |
|---------------------------------------------------------|--------|
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 220,18 |
|---------------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                               |      |
|-------------------------------|------|
| Roof, Scratch(es), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 462,35 |
|---------------------------------------------------------------------|--------|





