



RENAULT CLIO: 1LUV905

Vinnumber:	VF15R0J0A54168211	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	11/12/2015	Fiscalpower:	
Expertise Mileage:	94699	Power Kw:	66
Bodytype:		Body color	Red
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	PARKING KT
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	185/65/15/92 MS Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	811,32
Ignition key, Broken, E - Replace	150,00





Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Smart repair 110,64



Wheel cover F L, Scratch(es), E - Replace 24,00



Instrument panel cover, Damaged, Acceptable 0,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, LI - Repair and paint (complete) 0,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Forfeit 115,56



Rocker panel inner R R, Scratch(es), Forfeit 115,56

