



OPEL Astra: 1JFH525

Vinnumber:	W0LPC6DA6FG021722	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	2/12/2014	Fiscalpower:	
Expertise Mileage:	100416	Power Kw:	70
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	VOOR
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/60/16/92 MS Steel			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	916,63
-------------------	--------

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)		0,00
		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Door R L, Chemical polution, LI - Repair and paint (complete)		318,35
		