



VOLKSWAGEN Golf Sportsvan: 1HLR195

Vinnumber:	WVWZZZAUZFW523457	Versionname:	GOLF SPORTSVAN Trendline 110PK
First Registrationdate:	21/08/2014	Fiscalpower:	
Expertise Mileage:	123603	Power Kw:	81
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3215
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 MS Steel				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	722,16
-------------------	---------------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F R, Scratch(es), E - Replace

30,00



Wheel cover R L, Scratch(es), E - Replace

30,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Wheel cover F L, Scratch(es), E - Replace

30,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display