



PEUGEOT Partner: 1DLE108

Vinnumber:	VF37A9HN0CN511018	Versionname:	PARTNER B/F L1H1 Conf.120 FAP(EU5)75PK
First Registrationdate:	14/06/2012	Fiscalpower:	
Expertise Mileage:	83184	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3526
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2086,44
-------------------	----------------

Interior, Damaged, Acceptable	0,00
-------------------------------	-------------





Door frame F L, Dent(s), It - Spot repair

115,56



Door frame F R, Dent(s), It - Spot repair

115,56



Rocker panel inner F L, Scratch(es), Forfeit

115,56



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display


Trunk door R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete)

433,13



Bumper R, Scratch(es), Smart repair

110,64



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Forfeit

115,56



Door seal F L, Deformed / Strained, E - Replace

46,50



Sill outer R, Dent(s), LI - Repair and paint (complete)

232,88



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper F, Scratch(es), Smart repair 110,64



Door seal F R, Deformed / Strained, E - Replace 46,50



Wing F R, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete) 262,76



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display