



## VOLKSWAGEN GOLF VARIANT: 1NVD422

Vinnumber:	<b>WVWZZZAUZGP620780</b>	Versionname:	<b>1.6 TDI 81KW HIGHLINE</b>
First Registrationdate:	<b>3/05/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>211858</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 600 KM</b>	Parking lot:	<b>EX POOL</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1011,36</b>
Alloy rim R L polished, Rust, LI - Repair and paint (complete)			<b>95,00</b>



Door R R, Dent(s), Acceptable

0,00



Rear window, Scratch(es), E - Replace

370,00



Alloy rim F R polished, Rust, LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Rust, LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Rust, LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), It - Spot repair

115,56



Wing R L, Dent(s), PDR - Paintless dent repair

82,80



Roof, Dent(s), PDR - Paintless dent repair

63,00

