



VOLKSWAGEN PASSAT VARIANT: 1LKS863

Vinnnumber:	WVWZZZ3CZGE085991	Versionname:	2.0 TDI VARIANT HIGHLINE
First Registrationdate:	14/10/2015	Fiscalpower:	
Expertise Mileage:	66816	Power Kw:	110
Bodytype:	Break	Body color:	BRUIN
Gearbox:	MAN 6 VIT	Body color:	Dark Brown
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	11500 KM	Oil level:	OK
Maintenance:	OK	Parking lot:	4812
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/98 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	No	Compressor	No
Emergency spare wheel	No	Jack	No
Repair kit	No	Runflat	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 657,91

Bonnet, Chemical polution, Cleaning 37,55



Bumper F, Dent(s) and scratch(es), It - Spot repair 163,56



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Window R L door, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Crack, E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Compressor, Missing, E - Replace 0,00

