



**VOLVO V60: 1NEL695**

|                                    |                          |              |                       |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber:                         | <b>YV1FW79C1G1317478</b> | Versionname: | <b>2.0 D3 KINETIC</b> |
| First Registrationdate:            | <b>4/02/2016</b>         | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>36836</b>             | Power Kw:    | <b>110</b>            |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>             |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>PARKING GARAGE</b> |
| Battery functioning:               | <b>Yes</b>               |              |                       |
| Number of doors:                   | <b>5</b>                 |              |                       |
| Number of seats:                   | <b>5</b>                 |              |                       |
| Number head rests:                 | <b>5</b>                 |              |                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                       |
| Category:                          | <b>Passenger Car</b>     |              |                       |
| Oil level:                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                       |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Rear parking sensors             |
| Cruise Control                 |                                  |
| Steering wheel multifunctional |                                  |
| Type of headlighting           | <b>Headlighting Halogen</b>      |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/92 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |             |
|--|-------------|
| Total cost ex VAT                                      | <b>0,00</b> |
| Bumper R, Bad repair, LI - Repair and paint (complete) | <b>0,00</b> |



Rear window, Scratch(es), Acceptable

0,00



Wing F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Bad repair, LI - Repair and paint (complete)

0,00

