


**RENAULT CLIO: 1LVF578**

Vinnumber:	<b>VF15RKJ0A53921989</b>	Versionname:	<b>1.5 ENERGY DCI 90 COMMUNITY</b>
First Registrationdate:	<b>15/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>149268</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>GEBOUW BUUR</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/55/16/92 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	680,18
Maintenance, Maintenance, Execute	0,00

*No pictures to display*

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	193,44
---------------------------------------------------------------------	--------



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace 0,00



Bonnet, Dent(s), LI - Repair and paint (complete) 232,06



Wheel cover R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Wheel cover F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*