



MERCEDES C 200 : 1HZR636

Vinnumber:	WDD2050371F117813	Versionname:	C BER 200 BlueTEC 136PK
First Registrationdate:	7/11/2014	Fiscalpower:	
Expertise Mileage:	118828	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	B7 219 JOURS	Parking lot:	4705
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	925,36
Rearview mirror housing R, Bad repair, LI - Repair and paint (complete)	115,56



Door R R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Wing F L, Scratch(es), Acceptable

0,00



Seat cover F L, Tear, E - Replace

360,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Backrest cover F L, Worn, Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Dent(s), Acceptable

0,00

