



TOYOTA AVENSIS TOURING SPORTS: 1LVU941

Vinnumber:	SB1EN76L30E008974	Versionname:	1.6 D-4D BUSINESS PLUS
First Registrationdate:	18/12/2015	Fiscalpower:	
Expertise Mileage:	179254	Power Kw:	82
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	MIN 2170 KM	Parking lot:	2615
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/98 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1066,80
-------------------	----------------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Sill outer R, Crack, Le - Replace and paint	712,00
---	--------



Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F L, Repaired, Acceptable	0,00
--------------------------------	------



Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display