



MERCEDES A: 1KVN491

Vinnumber:	WDD1760421V091536	Versionname:	1.6 A 180
First Registrationdate:	14/07/2015	Fiscalpower:	
Expertise Mileage:	150136	Power Kw:	90
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1112
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 0,00

Dashboard, Glue residues, Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace

0,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Roof pillar L, Chemical pollution, 67 - Polish

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

SD card, Missing, E - Replace

0,00



Rearlight R , Broken, E - Replace

0,00



Full screen GPS, Not functioning (well), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00





Wheel cover R L, Scratch(es), E - Replace

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door panel F L, Worn, Acceptable

0,00



Roof, Chemical polution, 67 - Polish

0,00

No pictures to display