



RENAULT ESPACE: 1LGF455

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF1RFC00853580769 | Versionname: | 1.6 DCI 160 EDC ENERGY INITIALE PARIS |
| First Registrationdate: | 21/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 189698 | Power Kw: | 118 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3210 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Windows electric F | Panoramic roof |
| Windows electric R | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunctional | Front parking sensors |
| Seats F heated | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/55/19/19 MS LightMetal | | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|---------------------------------------|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 63,00 |
| Rear window, Scratch(es), E - Replace | | | 0,00 |



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, LI - Repair and paint (partial) 0,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Bonnet, Chemical polution, 67 - Polish 0,00

