



VOLKSWAGEN GOLF SPORTSVAN: 1JAJ605

Vinnumber:	WVWZZZAUZEW508492	Versionname:	1.6 TDI 81KW HIGHLINE BMT
First Registrationdate:	17/11/2014	Fiscalpower:	
Expertise Mileage:	122105	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2222
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal			
Summer tyres:	Fr.L. BF Goodrich: 5 mm	Fr.R. BF Goodrich: 5 mm	
	Re.L. BF Goodrich: 6 mm	Re.R. BF Goodrich: 6 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	707,48
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ceiling, Stain, Cleaning	25,00
--------------------------	-------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Chemical polution, 67 - Polish	0,00
--	------

No pictures to display

Protection plate M, Missing, E - Replace	74,00
--	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), 67 - Polish 0,00

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (partial) 0,00



Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

