



VOLKSWAGEN Passat: 1FPX634

Vinnnumber:	VWVZZZ3CZEE036488	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	19/09/2013	Fiscalpower:	
Expertise Mileage:	140837	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4728
Maintenance:	9600		
Maintenance:	222 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	250,00
-------------------	--------

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display	
------------------------	--

Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Glove compartment lid, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Towhook, Missing, E - Replace	250,00



Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tires, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R, Dirty, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Acceptable	0,00
<i>No pictures to display</i>	
Electricity circuit, Not functioning (well), P - Check	0,00

